

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	202268	340/425.5, 426, 539, 428.ccls	USPAT; US-PGPUB; EPO; JPO	2003/06/02 16:36	
2	BRS	L2	537	1 and vehicle adj4 theft	USPAT; US-PGPUB; EPO; JPO	2003/06/02 16:37	
3	BRS	L3	224791	1 and vehicle	USPAT; US-PGPUB; EPO; JPO	2003/06/02 16:38	
4	BRS	L4	6739	3 and cellular	USPAT; US-PGPUB; EPO; JPO	2003/06/02 16:38	
5	BRS	L5	1934	1 and service adj provider	USPAT; US-PGPUB; EPO; JPO	2003/06/02 16:39	
6	BRS	L6	183	4 and service adj provider	USPAT; US-PGPUB; EPO; JPO	2003/06/02 16:39	
7	BRS	L7	6	5 and dome adj light	USPAT; US-PGPUB; EPO; JPO	2003/06/02 16:39	

	Error Definition	Er ro rs
1		0
2		0
3		0
4		0
5		0
6		0
7		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
8	BRS	L8	6	6 and dome adj light	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 16:51	
9	BRS	L9	1881	340/426	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 16:51	
10	BRS	L10	84	9 and dome adj light	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 16:52	
11	BRS	L11	26	10 and cellular	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:08	
12	BRS	L12	977	340/522	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:09	
13	BRS	L13	225	12 and vehicle	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:09	
14	BRS	L14	9	13 and ignition and dome	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:56	

	Error Definition	Er ro rs
8		0
9		0
10		0
11		0
12		0
13		0
14		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
15	BRS	L15	94	( "2688865"   "3241344"   "3553448"   "3582639"   "3678716"   "3766539"   "3829693"   "3839640"   "3956732"   "3992909"   "4007955"   "4052716"   "4080812"   "4155233"   "4166955"   "4242669"   "4312197"   "4318089"   "4322959"   "4342210"   "4379971"   "4384207"   "4418335"   "4437003"   "4441023"   "4464649"   "4468657"   "4507654"   "4556796"   "4604524"   "4612442"   "4645233"   "4667990"   "4697081"   "4704533"   "4709153"   "4745284"   "4746910"   "4752768"   "4764755"   "4775347"   "4797657"   "4825079"   "4848114"   "4848509"   "4857912"   "4868390"   "4881148" )	USPA T	2003/06/02 17:11	
16	BRS	L16	23	( "4205300"   "4327444"   "4383242"   "4414541"   "4450437"   "4628400"   "4674454"   "4754255"   "4812814"   "4893240"   "5024186"   "5040990"   "5049867"   "5103221"   "5129376"   "5132660"   "5146215"   "5159334"   "5278547"   "5285186"   "5309144"   "5323140"   "5438312" ) . PN.	USPA T	2003/06/02 17:12	

	Error Definition	Er ro rs
15		0
16		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
17	BRS	L17	53	( "3174576" "3196440"   "3270831"   "3399554" "3590136"   "3635305"   "3703714" "3706966"   "3707697"   "3723967" "3866168"   "3891967"   "3891980" "3969709"   "3978478"   "4133405" "4137985"   "4143368"   "4151507" "4153127"   "4159466"   "4205325" "4240516"   "4333090"   "4342024" "4372410"   "4383242"   "4421190" "4463340"   "4505054"   "4573046" "4602256"   "4620268"   "4665397" "4670746"   "4672375"   "4688036" "4719460"   "4723121"   "4737784" "4754255"   "4760394"   "4761645" "4794268"   "4794368"   "4825210" "4835533"   "4853687"	USPA T	2003/06/0 2 17:13	
18	BRS	L24	370	340/428	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:57	
19	BRS	L25	60	24 and dome	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:57	
20	BRS	L27	11	26 and cellular	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:57	

	Error Definition	Er ro rs
17		0
18		0
19		0
20		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
21	BRS	L26	51	25 and ignition	USPA T; US-P GPUB ; EPO; JPO	2003/06/0 2 17:59	
22	BRS	L28	3	("2238246"   "2782396"   "2839736") .PN.	USPA T	2003/06/0 2 18:00	

	Error Definition	Er ro rs
21		0
22		0